Energy Performance Certificate (EPC)

Dwellings

Scotland

32 ORCHARD COURT, DUNDEE, DD4 9DB

Dwelling type: Date of assessment: Mid-terrace house

Date of certificate: Total floor area:

85 m²

Primary Energy Indicator:

30 May 2025 02 June 2025

208 kWh/m²/year

Reference number: Type of assessment:

Approved Organisation: Main heating and fuel:

are likely to be.

7808-1013-3205-6705-2204 RdSAP, existing dwelling

Elmhurst

Boiler and radiators, mains

gas


You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Control and the control of the last term of the control of the con		S BOOK NOW, THE SAME
Estimated energy costs for your home for 3 years*	£3,003	See your recommendations
Over 3 years you could save*	£537	report for more information

based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Current | Potential Venuenvironmentally friendly Jews- CO ::

Environmental Impact (CO₂) Rating

This graph shows the current efficiency of your home,

Your current rating is band C (72). The average rating

The potential rating shows the effect of undertaking all

of the improvement measures listed within your

taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills

Energy Efficiency Rating

for EPCs in Scotland is band D (61).

recommendations report.

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is band C (70). The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

very envi	ronmenta	ally friendly	- lower Co	0 ₂ emission	S	Current	Potential
(92 plus)	A						
(81-91)		B					86
(69-80)		(25			70	99
(55-68)			D			70	
(39-54				E			
(21-38)				F			
(1-20)					G		
Not enviro	nmentally	/ friendly -	higher CO	emissions	100000000000000000000000000000000000000		

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Party wall insulation	£300 - £600	£228.00
2 Floor insulation (suspended floor)	£800 - £1,200	£183.00
3 Solar water heating	£4,000 - £6,000	£123.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS** REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, partial insulation (assumed)	****	***
Roof	Pitched, 150 mm loft insulation	****	****
Floor	Suspended, no insulation (assumed)	_	_
Windows	Fully double glazed	***	***
Main heating	Boiler and radiators, mains gas	****	****
Main heating controls	Programmer, room thermostat and TRVs	****	****
Secondary heating	None	_	_
Hot water	From main system	****	****
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 37 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.1 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.5 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

over 3 years

Estimated en	ergy costs for this home		
•	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,394 over 3 years	£1,980 over 3 years	
Hot water	£345 over 3 years	£222 over 3 years	You could
Lighting	£264 over 3 years	£264 over 3 years	save £537

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

£2,466

Recommendations for improvement

Totals £3,003

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement	
		indicative cost	per year	Energy	Environment
1	Party wall insulation	£300 - £600	£76	C 74	C 73
2	Floor insulation (suspended floor)	£800 - £1,200	£61	C 76	C 75
3	Solar water heating	£4,000 - £6,000	£41	C 77	C 77
4	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£405	B 87	B 86

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Party wall insulation

Party wall insulation, to fill the cavity of a wall separating a dwelling from another building with an insulating material, reduces heat loss; this will improve levels of thermal comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the party wall, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work. This work has to comply with building regulations, including that installation will not adversely affect the performance of the existing wall in respect of noise transmission. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

4 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	10,105	(280)	N/A	N/A
Water heating (kWh per year)	1,785		•	

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:

Mr. Graeme Millar

Assessor membership number:

EES/022017 Allied Surveyors Scotland Ltd 8 Whitehall Crescent

Company name/trading name: Address:

Dundee

Phone number:

DD1 4AU 01382 349930

Email address:

gary.black@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



survey report on:

Property address	32 Orchard Court, Dundee, Angus, DD4 9DB
Customer	
Customer address	
Prepared by	Allied Surveyors Scotland Ltd
	Anica ourveyors occitand Ltd
Date of inspection	30th May 2025



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Χ

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
 or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities:
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a two storey mid-terraced villa with garden grounds.
Accommodation	GROUND FLOOR Entrance Hall, Living Room and Kitchen.
	FIRST FLOOR Landing, Three Bedrooms and Bathroom.
Gross internal floor area (m²)	85
Neighbourhood and location	The subjects form part of an established residential area where surrounding properties are of similar age and character. An adequate range of facilities and amenities can be found within a reasonable distance.
Age	Approximately 55 years.
Weather	Light rain.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	The chimney head is of brick construction with lead flashings and clay chimney pots.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe

Roofing including roof space	and reasonable to do so.
	The roof is of pitched timber design, overlaid with concrete tiles.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Rainwater fittings are run in uPVC and cast iron.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls of the property are of a form of construction known as Crosswall, consisting of brick party/gable walls with timber frame infill to front and rear elevations.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are of uPVC and aluminium double glazed type with timber surrounds.
	Main entrance doors to the property are of uPVC and aluminium double glazed type.
	Roof edge linings (fascia's and soffits) are formed in timber/uPVC.
	It is possible that soffit boards are formed in asbestos containing material, common practice at the time of construction. However, this can only be confirmed by sample analysis.
External decorations	Visually inspected.
	External timbers, cast iron components and masonry are stained/painted.
Conservatories / porches	Not applicable.
Communal areas	Not applicable.
Garages and permanent outbuildings	Not applicable.

Outside areas and boundaries	Visually inspected.
	The property benefits from private garden grounds to the rear bounded by timber fencing.
Ceilings	Visually inspected from floor level.
	Ceilings within the property appear to be of plasterboard.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls appear to be of plasterboard and hard plaster.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Floors are of suspended timber construction.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal joinery comprises timber skirtings, facings, linings and internal doors.
	The kitchen comprises a range of base and wall mounted units.
Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	Within the living room there is a gas fire.
Internal decorations	Visually inspected.
	Internal surfaces are papered/painted.

Cellars	Not applicable.
Electricity	Accessible parts of the wiring were viewelly increased with aut
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	A mains supply of electricity is connected with power points situated throughout the property. The fuse board is located in the entrance hall.
Gas	Acceptable market 641
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	A mains supply of gas is connected. The gas meter is located in an external meter box.
Water, plumbing, bathroom fittings	
water, plumbing, bathroom mungs	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Water is supplied from the mains. Where viewed the plumbing system is of uPVC and copper pipework.
	The bathroom contains a three piece suite consisting of bath with shower over, wash hand basin and w.c.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Heating is provided by a gas fired combination boiler, located in the landing cupboard, which serves hot water radiators located throughout the property. Hot water is provided directly from the boiler on demand.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is assumed to be to the main Local Authority sewer.

Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

Visually inspected.

No test whatsoever were carried out to any systems or appliances.

There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked.

Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required. The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.

We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor.

Any additional limits to inspection

For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

Areas of the property that were covered, unexposed or inaccessible have not been inspected. It cannot be confirmed that such areas are free from infestation, decay or other defects.

An external inspection was carried out from ground level within the boundaries of the property and from adjoining highways.

It was dry on the date of inspection. Leakage and water penetration within roof spaces, around chimney breasts, window openings, etc are sometimes only visible during or immediately after, adverse weather conditions.

A limited inspection was possible of the roof void.

A limited inspection of the sub floor area was possible.

No close inspection was possible to enclosed areas beneath and around washing appliances and sanitary fittings.

The report does not include an asbestos inspection. However,

Any additional limits to inspection


asbestos was widely used in the building industry until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported within the limitations of the inspection and should you have concerns you should engage a qualified asbestos surveyor.

It should be appreciated that further defects can arise after the date of our inspection.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- (1) Chimney pots
- (2) Coping stone
- (3) Chimney head
- (4) Flashing
- 5 Ridge ventilation
- (6) Ridge board
- 7) Slates / tiles
- (8) Valley guttering
- 9 Dormer projection
- (10) Dormer flashing
- (11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- (16) Insulation
- (17) Parapet gutter
- (18) Eaves guttering
- (19) Rainwater downpipe
- (20) Verge boards/skews
- (21) Soffit boards
- (22) Partition wall
- (23) Lath / plaster
- (24) Chimney breast
- 25) Window pointing
- (26) Window sills
- (27) Rendering
- 28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- (32) Subfloor ventilator
- (33) Damp proof course
- (34) Base course
- (35) Foundations
- (36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	On the basis of our single limited inspection there is no evidence of recent or ongoing movement affecting the subjects.

Dampness, rot and infestation	
Repair category	1
Notes	There is no evidence of dampness, rot or infestation affecting accessible areas.

Chimney stacks	
Repair category	2
Notes	Chimney stacks are affected by weathering and erosion, typical of the age and type of construction. Ongoing maintenance should be anticipated.

Roofing including roof space	
Repair category	2
Notes	The roof covering appears to be the original and is affected by weathering, consistent with age.
	There is a build up of moss growth on the roof covering which restricted our inspection of the roof surface. Moss growth can foreshorten the anticipated life of roof coverings.
	Given the age and type of the roof, it would be recommended that a reputable Roofing Contractor is instructed to inspect the roof and advise on any repairs required and anticipated remaining life span.

Rainwater fittings	
Repair category	2
Notes	Vegetation growth was noted to gutters. It should be noted that it was not raining heavily at the time of inspection. We are therefore unable to confirm that all gutter joints, downpipes etc are free from leaks or other defects.

Main walls	
Repair category	2
Notes	Areas of rot were noted to timber infill panels to front and rear elevations. Repairs are now required.

Windows, external doors and joinery	
Repair category	3
Notes	The windows are of dated type and are affected by wear and tear, including loose ironmongery and defective opening mechanisms.
	Windows generally require careful ongoing maintenance and with the passage of time can be prone to the failure of mechanisms and seals.
	External doors are of dated type and are affected by wear and tear.
	Extensive areas of rot were noted to external timbers.
	It is possible that soffit boards are formed in asbestos containing material, common practice at the time of construction. However, this can only be confirmed by sample analysis.

External decorations	
Repair category	3
Notes	External decorations are weathered. Renewal will be required.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	-
Notes	Not applicable.

Outside areas and boundaries	
Repair category	1
Notes	Outside areas and boundaries appear adequately maintained.

Ceilings	
Repair category	1
Notes	Hairline cracking was noted to some ceiling surfaces. Unevenness and hairline cracking was noted to some ceiling surfaces. Ceilings within the upper landing and bathroom have been overclad in uPVC and timber. It is not possible to comment on the condition of concealed, original ceiling finishes.

Internal walls	
Repair category	1
Notes	Unevenness and hairline cracking was noted to some wall surfaces. Localised plaster repairs may be required upon redecoration.

Floors including sub-floors	
Repair category	2
Notes	Some floorboards were noted to be loose and uneven underfoot.

Internal joinery and kitchen fittings	
Repair category	2
Notes	Internal joinery is of mixed vintage and, whilst affected by wear and tear, appears in generally serviceable condition. Kitchen units are dated and affected by wear and tear. Repairs/upgrades are likely to be required.

Chimney breasts and fireplaces	
Repair category	3
Notes	The gas fire appears to have been decommissioned. We would recommend that the gas fire is tested/serviced by a qualified gas engineer prior to use.

Internal decorations	
Repair category	3
Notes	The property would benefit from a programme of redecoration.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	3
Notes	The electrical installation is dated with a number of features which will not comply with current regulations. Upgrades are likely to be required.
	It is recommended that electrical installations are checked by a qualified electrician every five years, or upon a change of ownership, at which point further repairs/upgrades may be identified.

Ø Gas	
Repair category	3
Notes	We understand that the gas fire has been disconnected and the supply capped off. This should be confirmed by a qualified gas engineer.
	Gas fittings have not been tested. We would recommend that all gas

Gas	
Repair category	3
Notes	fittings/appliances are tested by a suitably qualified gas engineer prior to first use and annually thereafter.

Water, plumbing and bathroom fittings	
Repair category	2
Notes	Sanitary fittings are dated and affected by wear and tear.
	Sealant around the bath is beginning to deteriorate. It is important to maintain sealant/tile grout around baths and shower trays in order to prevent water ingress to concealed areas.
	It should be noted that no inspection was possible to the area below the bath due to the presence of a fitted bath panel.

Heating and hot water								
Repair category	3							
Notes	The heating system appears to have been decommissioned and should only be recommissioned by a qualified gas engineer.							
	It is recommended that gas boilers are serviced on an annual basis by a qualified gas engineer. This should be regarded as a routine safety and maintenance check. Purchasers are advised to obtain any previous service documentation.							

Drainage	
Repair category	1
Notes	Visible, above ground drainage pipes appear in reasonable order. There was no evidence at the time of inspection to suggest that the system was choked or leaking.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	3
External decorations	3
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	2
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	3
Internal decorations	3
Cellars	-
Electricity	3
Gas	3
Water, plumbing and bathroom fittings	2
Heating and hot water	3
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground and First
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes No X
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchases contracts, further specialist advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

The subjects should be insured for a sum of not less than £265,000

THE RESERVE OF THE PARTY OF THE	NORTH TOTAL PROPERTY OF			
Valuation	21010	1000 12 200	COMMISSION	Sing
m activity for the	III - I II L I I	m a m (- 1 m / 1 - 1		1-111-1

Market value assuming vacant possession £110,000

Signed	Security Print Code [437095 = 0566] Electronically signed
Report author	Graeme Millar
Company name	Allied Surveyors Scotland Ltd
Address	8 Whitehall Crescent, Dundee, DD1 4AU
Date of report	13th August 2025



Property Address												
Address	32 Orchard Cour	32 Orchard Court, Dundee, Angus, DD4 9DB										
Seller's Name Date of Inspection	30th May 2025	30th May 2025										
Property Details												
Property Type	X House Coach Converted flat	Bungalow Studio Tenement flat	Chalet Converted maison Flat over non-resid	ette Purpose bu	uilt maisonette uilt flat cify in General Remarks)							
Property Style	☐ Detached☐ Back to back	Semi detached High rise block	X Mid terrace Low rise block	End terrace Other (spec	e cify in General Remarks)							
Does the surveyor be e.g. local authority, n	elieve that the prop nilitary, police?	erty was built for	the public sector,	X Yes	No							
Flats/Maisonettes on	ly Floor(s) on which	located	No. of floors in blo		Yes No							
Approximate Year of	Construction 1970)	No. of units in bloc	К []								
Tenure												
X Absolute Ownership	Leasehold	Ground rent £	Unexpir	ed years								
Accommodation												
Number of Rooms	1 Living room(s) 1 Bathroom(s)	3 Bedroom(s) 0 WC(s)	1 Kitchen(s) 0 Other (Specify in	General remarks)								
Gross Floor Area (ex			m² (Internal)	98 m² (External)								
Residential Element	(greater than 40%)	X Yes No										
Garage / Parking /	Outbuildings											
Single garage Available on site?	Double garage Yes No	Parkir	ng space	X No garage / garage	space / parking space							
Permanent outbuildin	igs:											
None.												

Construction							
Walls	Brick	Stone	Concrete	Timber frame			
Roof	∐ Solid X Tile	Cavity Slate	Steel frame Asphalt	Concrete block	C 🔼 Oth	er (specify in Ge	neral Remarks)
	Lead	Zinc	Artificial sla		Oth	er (specify in Ge	neral Remarks)
Special Risks							
Has the property s	suffered structu	ral movement	?			Yes	X No
If Yes, is this rece	nt or progressiv	e?				Yes	No
Is there evidence, immediate vicinity	history, or reas ?	on to anticipa	te subsidence,	heave, landslip	or flood in th	e Yes	X No
If Yes to any of the	e above, provid	e details in Ge	eneral Remarks	S.			
Service Connec	tion						
Based on visual in of the supply in Ge	spection only. I eneral Remarks	f any services	appear to be r	non-mains, pleas	e comment	on the type a	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description of	f Central Heatin	g:					
Gas fired boiler.							-
							_
				=======================================	-×	<u> </u>	
Site							
Apparent legal issu	ues to be verifie	d by the conv	eyancer. Pleas	se provide a brief	description	in General Re	emarks.
Rights of way	Shared drives	/ access	Garage or other a	menities on separate	site Sha	red service conn	ections
Agricultural land inc	luded with property		Ill-defined bounda	ries	Oth	er (specify in Ger	neral Remarks)
Location							
X Residential suburb	Reside	ential within town	/ city Mixed	residential / commer	rcial Mai	nly commercial	
Commuter village	Remot	e village	Isolate	ed rural property	Othe	er (specify in Ger	neral Remarks)
Planning Issues							
Has the property b	een extended /	converted / al	Itered?	es X No			
If Yes provide deta	ils in General F	Remarks.					
Roads							
X Made up road [Unmade road	Partly com	pleted new road	Pedestrian a	ccess only	Adopted	Unadopted

General Remarks	
Construction: Crosswall construction. At the time of inspection the subjects were foun maintenance required.	d to be in a poor state of repair with a number of works of
Essential Repairs	
None.	
Estimated cost of essential repairs £	Retention recommended? Yes X No Amount £

Comment on Mortgagea	ibility						
The subjects form suitable	e security for mortgage purposes, subject to individual lender criteria.						
Valuations							
Market value in present cor	adition	£ 110.000					
Market value on completion		£ 110,000 }					
Insurance reinstatement va	*	£ 265,000					
	(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)						
Is a reinspection necessary	· · · · · · · · · · · · · · · · · · ·	Yes X No					
Buy To Let Cases							
What is the reasonable rang month Short Assured Tenar	ge of monthly rental income for the property assuming a letting on a 6 ncy basis?	£ N/A					
Is the property in an area w	here there is a steady demand for rented accommodation of this type?	Yes No					
Declaration							
Signed	Security Print Code [437095 = 0566] Electronically signed by:-						
Surveyor's name	Graeme Millar						
Professional qualifications	MRICS						
Company name	Allied Surveyors Scotland Ltd						
Address	8 Whitehall Crescent, Dundee, DD1 4AU						
Telephone	01382 349930						
Fax							

Report date

13th August 2025

Property Questionnaire

PROPERTY ADDRESS:

32 Orchard Court Dundee Angus DD4 9DB

SELLER(S):

Asset Management Group

COMPLETION
DATE OF
PROPERTY
QUESTIONNAIRE:

03.06.2025

>> NOTE FOR SELLERS

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

nformation to be given to prospective buyer(s) 1. Length of ownership												
How long have you owned the property?												
The Seller is not the registered owner, but is selling the property as mortgagee in possession, under powers of sale conferred by the original mortgage												
2. Council Tax												
Which Council Tax band is your property in? please circle												
The Seller, a	s mortgagee in	posse	ession	does n	ot kn	ow. P	lease (enquii	e at	the C	ouncil.	
		Α	В	C I	D	E	F	G	Н			
3. Parking											9.	
What are the	arrangements fo	r park	ing at y	your pro	perty'	? tick all	that app	ly				
The Seller, as rely on their	s mortgagee in own enquiries	posse and in	ession specti	has no on.	pers	onal k	nowle	dge o	f the	prop	erty. Th	e buyer must
G	arage	1			Allo	ocated	parkin	g spa	се			
D	riveway				Sh	ared p	arking			-0, H		
0	n street				Re	sident	permit					
М	etered parking				Oth	n er pleas	se specify					
4. Conser	vation Area											
Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)? Don't know. Please rely on own enquiries												
5. Listed E	Buildings											
ls your proper approved as b	ty a Listed Build peing of special a	ing, or archite	contai ctural c	ned with or histori	nin on cal in	e (i.e. terest)	a build ?	ing red	cogn	ised a	nd	Don't know. Please rely on own enquiries

A	terations / additions / extensions	
(i	During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	As mortgagee possessio the seller ha no persona knowledge Please rely on own inspection
lf y	ou have answered yes, please describe the changes which you have made:	
(i	i) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Not known Please rely on own enquiries
	ou do not have the documents yourself, please note below who has these documents licitor or estate agent can arrange to obtain them.	s and your
yo	ive you had replacement windows, doors, patio doors or double glazing installed in ur property? You have answered yes, please answer the three questions below:	As mortgagee i possession the seller ha no persona knowledge, Please rely inspection
(i)	Were the replacements the same shape and type as the ones you replaced?	As above
(ii)	Did this work involve any changes to the window or door openings?	As above
(iii)	Please describe the changes made to the windows doors, or patio doors (with appro- when the work was completed):	oximate dates
	please give any guarantees which you received for this work to your solicitor or esta	te agent.

7.	Central heating	
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).	As mortgagee in possession the seller has no personal knowledge. Please rely on own inspection
	If you have answered yes/partial — what kind of central heating is there? (Examples: gas-fire electric storage heating, gas warm air.)	ed, solid fuel,
	If you have answered yes, please answer the 3 questions below:	
b	When was your central heating system or partial central heating system installed?	
С	Do you have a maintenance contract for the central heating system?	As mortgagee in possession, no circle answer
	If you have answered yes, please give details of the company with which you have a ma greement:	
d	When was your maintenance agreement last renewed? (Please provide the month and y	rear).
8.	Energy Performance Certificate	
Does	your property have an Energy Performance Certificate, which is less than 10 years	The Home Report will contain this
9.	Issues that may have affected your property	

а	Has there been any storm, floo you have owned it?	d, fire or other struct	ural damage to your prop	perty while	As mortgagee in possession the seller has no personal knowledge. Please rely on own inspection
	If you have answered yes, is the claim?	ne damage the subjec	ct of any outstanding inst	urance	As above
b	Are you aware of the existence	of asbestos in your p	property?		As above
	If you have answered yes, plea	ase give details:			
10. a	Services Please tick which services are of the seller, as mortgagee in posowner				
	Please tick which services are of the seller, as mortgagee in pos				
	Please tick which services are of the seller, as mortgagee in posowner	ssession, cannot co	mment on arrangements		
	Please tick which services are of the seller, as mortgagee in posowner Services	ssession, cannot co	mment on arrangements		
	Please tick which services are of the seller, as mortgagee in posowner Services Gas / liquid petroleum gas	ssession, cannot co	mment on arrangements		
	Please tick which services are of the seller, as mortgagee in posowner Services Gas / liquid petroleum gas Water mains / private water supply	ssession, cannot co	mment on arrangements		
	Please tick which services are of the seller, as mortgagee in posowner Services Gas / liquid petroleum gas Water mains / private water supply Electricity	ssession, cannot co	mment on arrangements		
	Please tick which services are of the seller, as mortgagee in posowner Services Gas / liquid petroleum gas Water mains / private water supply Electricity Mains drainage	ssession, cannot co	mment on arrangements		

b	Is there a septic tank system at your property?	As mortgagee in possession the seller has no personal knowledge. Please rely on own inspection
	If you have answered yes, please answer the two questions below:	
С	Do you have appropriate consents for the discharge from your septic tank?	As above
d	Do you have a maintenance contract for your septic tank?	As above
11.	If you have answered yes, please give details of the company with which you have a macontract: Responsibilities for Shared or Common Areas	aintenance
а	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	As mortgagee in possession the seller has no personal knowledge. Please rely on own inspection
	If you have answered yes, please give details:	
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	As above
	If you have answered yes, please give details:	
С	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	As above

d	Do you have the right to walk over any of your neighbours' property – for example to put out your rubbish bin or to maintain your boundaries?	As above
	If you have answered yes, please give details:	1
е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	As above
	If you have answered yes, please give details:	
f	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	As above
	If you have answered yes, please give details:	
12.	Charges associated with your property	
а	Is there a factor or property manager for your property?	As mortgagee in possession the seller has no personal knowledge.
		Please rely on your own enquiries.
	If you have answered yes, please provide the name and address and give details of an and approximate charges:	y deposit held
b	Is there a common buildings insurance policy?	As above

	<u>If you have answered yes</u> , is the cost of the insurance included in your monthly/annual factor's charges?			
С	Please give details of any other charges you have to pay on a regular basis for the upkareas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.			
	As mortgagee in possession the seller has no personal knowledge. Please rely on your own enquiries.			
12	Specialist Works			
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?			
	As mortgagee in possession the seller has no personal knowledge. Please rely on own inspection			
	If you have answered yes, please say what the repairs were for, whether you carried ou (and when) or if they were done before you bought the property	t the repairs		
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	As above		
	If you have answered yes, please give details			
С	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	As above		
	If you have answered yes, these guarantees will be needed by the purchaser and should your solicitor as soon as possible for checking. If you do not have them yourself <u>please who has these documents</u> and your solicitor or estate agent will arrange for them to be obwill also need to provide a description of the work carried out. This may be shown in the cestimate.	<u>vrite below</u> otained. You		
	Guarantees are held by:			
14.	Guarantees			
a	Are there any guarantees or warranties for any of the following: circle answers			
	As mortgagee in possession the seller has no personal knowledge. Please rely on you enquiries.	rown		

		,				
(i)	Electrical work	No	Yes	Don't Know	With title deeds	Lost
(ii)	Roofing	No	Yes	Don't Know	With title deeds	Lost
(iii)	Central heating	No	Yes	, Don't know	With title deeds	Lost
(iv)	NHBC	No	Yes	Don't know	With title deeds	Lost
(v)	Damp course	No	Yes	Don't know	With title deeds	Lost
(vi)	Any other work or installations?	140	165	DOTT KITOW	viin the deeds	LOSI
,	(for example, cavity wall insulation, underpinning, indemnity policy)	No	Yes	Don't know	With title deeds	Lost
b	If you have answered 'yes' or which the guarantee(s) relate(s)		leeds', pleas	e give details of th	e work or installat	ons to
		" = -				
С	Are there any outstanding claim	s under any	of the guara	ntees listed above	? A	s above
	If you have answered yes, pleas	se give deta	iils:			
	, , , , , , , , , , , , , , , , , , , ,	3				
THE RESIDENCE OF THE PARTY OF T	Boundaries ar as you are aware, has any bou	ndary of you	ır property be	een moved in the la	ast 10	
years	s?					
	ortgagee in possession the selle enquiries and inspection.	er has no pe	ersonal know	ledge. Please rely	on your	
	lf you have answered yes, pleas	se give deta	ils:			
	Z - V '- V					
L						
	Notices that affect your prope					
In the	e past 3 years have you ever rece	ived a notic	e:			
	ortgagee in possession the selle enquiries	er has no pe	rsonal know	ledge. Please rely	on your	
а	advising that the owner of a neig	hbouring pr	operty has m	ade a planning app	olication? A	s above
b	that affects your property in som	e other way	?		A	s above

С	that requires you to do any maintenance, repairs or improvements to your property?	As above
	If you have answered ves to any of a-c above, please give the notices to your solicitor agent, including any notices which arrive at any time before the date of entry of the purch property.	or estate lase of your
I / We	aration by the seller(s)/or other authorised body or person(s): e confirm that the information in this form is true and correct to the best of my/our knowledge.	ıowledge
	ature(s):	
On be	ehalf of the Seller as Mortgagee in Possession	
Date:	As on front page	